## U.S. ENVIRONMENTAL PROTECTION AGENCY REMOVAL ACTION

### ADMINISTRATIVE RECORD FOR

# WEST VERMONT DRINKING WATER CONTAMINATION SITE SPEEDWAY, MARION COUNTY, INDIANA

#### ORIGINAL MAY 13, 2010 SEMS ID: 904866

NO.	SEMS ID	<u>DATE</u>	<u>AUTHOR</u>	RECIPIENT	TITLE/DESCRIPTION	<u>PAGES</u>
1	363300	07/01/06	ATSDR	Public	ATSDR Tox Fact Sheet: Vinyl Chloride Cas#75-01-4	1
2	363301	10/08/09	McDaniel, K., IDEM	Gebien, C., U.S. EPA	IDEM E-Mail Message Re: IDEM Request For U.S. EPA Assistance W/Reply History	5
3	363302	12/01/09	Marion County Health Dept.	U.S. EPA	MCHD Analytical Results For Residential Drinking Water (6/09-12/09)	55
4	363303	02/22/10	Schlieger, B., U.S. EPA	Atkinson, H., IDEM	EPA Letter Re: EPA Request For IDEM To Identify Any/All ARARs	1
5	363304	05/13/10	Schlieger, B., U.S. EPA	Karl, R., U.S. EPA	EPA Action Memo - Documentation & Justification Of An Emergency Removal Action Conducted At West Vermont Drinking Water Contamination Site (PORTIONS OF THIS DOCUMENT HAVE BEEN REDACTED)	14

#### UPDATE #1 SEPTEMBER 26, 2011

<u>NO.</u>	SEMS ID	<u>DATE</u>	<u>AUTHOR</u>	RECIPIENT	TITLE/DESCRIPTION	<u>PAGES</u>
1	409780	1111-01-0	1ARCADIS	File	ARCADIS - RCRA Facility Investigation Report For Allison Transmission, Inc.	34

<u>NO.</u>	SEMS ID	DATE	AUTHOR	RECIPIENT	TITLE/DESCRIPTION	Page 2 <u>PAGES</u>
2	409781	07/01/06	ATSDR	File	ATSDR - Tox FAQs Sheet For Vinyl Chloride Cas #75-01-4	2
3	409782	04/01/07	Mundell, J., Mundell & Associates, Inc.	Brittain, E., IDEM	Mundell & Associates - Further Site Investigation Addendum I, Michigan Plaza	235
4	409783	04/30/10	Mundell, J., Mundell & Associates, Inc.	Brittain, E., IDEM	Mundell & Associates - Quarterly Monitoring Progress Report - 1st Quarter 2010 Michigan Plaza W/Cover Letter	137
5	409784	08/12/10	KERAMIDA, Inc.	IDEM	KERAMIDA - Remediation System Evaluation Report April - June 2010 - Former General Motors Corporation, Allison Gas Turbine Division, Plant 10	661
6	409785	03/12/11	Weston Solutions, Inc.	U.S EPA	Weston Solutions Technical Memorandum Re: Analytical & Hydrogeological Evaluation	148
7	409779	09/26/11	[ATKOCIUNAS , PAUL ]	Karl, R., U.S. EPA	EPA Action Memo - Request For Approval And Funding For A Time-Critical Removal Action At The West Vermont Drinking Water Contamination Site (PORTIONS OF THIS DOCUMENT HAVE BEEN REDACTED)	

# **UPDATE #2 AUGUST 8, 2013**

<u>NO.</u>	SEMS ID	<u>DATE</u>	<u>AUTHOR</u>	RECIPIENT	TITLE/DESCRIPTION	<u>PAGES</u>
1	437067	00/00/00	MCHD	File	MCHD Spreadsheet Re: Residential Well Results (MS Excel File)	

<u>NO.</u>	SEMS ID	<u>DATE</u>	AUTHOR	RECIPIENT	TITLE/DESCRIPTION	Page 3 PAGES
2	437080	03/16/12	ARCADIS	Anderson, C., IDEM	Mundell & Assoc Letter Re: Response To IDEM's Request For Revised Remediation Work Plan Approval Review And Technical Response To General Notice Of Potential Liability Review For Michigan Plaza	75
3	437069	00/00/00	U.S. EPA	File	EPA Technical Fact Sheet Re: Vinyl Chloride	3
4	437070	06/01/97	U.S. EPA	File	EPA - Excerpt Form RI Report For North Belmont PCE Site, NC: Section 5 Contaminated Fate And Transport	15
5	437071	06/03/97	Flour Daniel General GTI	General Motors Corp.	Fluor Daniel GTI - FS Report (Draft) For General Motors- Allison Gas Turbine Plant 10	49
6	902228	09/01/97	ATSDR	File	Tox FAQs Sheet For Tetra- Chloroethylene Cas #127-18- 4	2
7	437072	10/30/02	KERAMIDA Environmental, Inc.	IDEM	KERAMIDA - Remediation Work Plan For Former General Motors Corp Allison Gas Turbine Div Plant 10 Vol 1	434
8	437073	12/01/06	Lothe, L., & J. Mundell, Mundell & Associates Inc.	O'Callaghan, J., IDEM	Mundell & Assoc Letter Re: Further Site Investigation At Michigan Plaza	38
9	409782	04/01/07	Mundell, J., Mundell & Associates, Inc.	Brittain, E., IDEM	Mundell & Associates - Further Site Investigation Addendum I, Michigan Plaza	235
10	437074	02/22/08	Mundell & Associates, Inc.	McInerny, D., Bose, McKinney & Evans, LLP	Mundell & Associates - Remediation Work Plan For Michigan Plaza	142

						AIXII
<u>NO.</u>	SEMS ID	<u>DATE</u>	AUTHOR	RECIPIENT	TITLE/DESCRIPTION	Page 4 PAGES
11	437075	10/31/09	Lothe, L., & J. Mundell, Mundell & Associates Inc.	Brittain, E., IDEM	Mundell & Associates Letter Re: Quarterly Monitoring Progress Report 1st Quarter 2009 For Michigan Plaza	599
12	437076	01/22/10	Brittain, E., R. Harris, Genuine Parts Company	Brittain, E., IDEM	IDEM Letter Re: Additional Investigation Request For Genuine Parts, Michigan Plaza And Allison Transmission Plant 12	2
13	902229	04/19/10	Weston Solutions. Inc.	File	Data Validation Report For The West Vermont Street Site	15
14	901047	01/14/11	Favero, D., Favero Geosciences	Heller, D., U.S. EPA	Favero Geosciences - Fourth Quarter 2010 Progress Report - RCRA Corrective Action - Allison Transmission	1033
15	409785	03/12/11	Weston Solutions, Inc.	U.S. EPA	Weston Solutions Tech Memo Re: Analytical & Hydrogeological Evaluation	148
16	437077	01/01/12	ENVIRON International Corporation	IDEM	ENVIRON - Remedial Progress Report For Former Allison Plant 10	396
17	437078	01/31/12	Webb, S. & J. Mundell, Mundell & Associates, Inc.	Anderson, C., IDEM	Mundell & Assoc Letter Re: Quarterly Monitoring Progress Report, Fourth Quarter 2011 For Michigan Plaza	258
18	437079	02/10/12	Lam, S., U.S. EPA	Hauer, G., IDEM	EPA Letter Re: Request For ARARs For West Vermont Drinking Water Contamination Site	2
19	902238	02/14/12	Kasarabada, P., IDEM	Lam, S., U.S. EPA	Letter Re: IDEM Response To U.S. EPA Request For State ARARs For The West Vermont Site	2
20	437081	05/21/12	Webb, C., IDEM	Mundell, J., Mundell & Associates, Inc.	IDEM E-Mail Message Re: Revised Work Plan For 3rd Round Of Cap For Michigan Plaza	2

<u>NO.</u>	SEMS ID	<u>DATE</u>	AUTHOR	RECIPIENT	TITLE/DESCRIPTION	Page 5 PAGES
21	437082	07/03/12	U.S. EPA	File	EPA - In The News- Technology Innovation News Survey: U.S. EPA Contamination Site Cleanup Information	1
22	904786	01/30/13	Weston Solutions, Inc.	U.S. EPA	Technical Memorandum: Analytical And Hydrogeological Evaluation For The West Vermont Street Contamination Site	448
23	904854	06/16/11	Weston Solutions, Inc.	U.S. EPA	Weston Solutions Title Search Report Re: West Vermont Water Contamination Site Genuine Auto Parts Property, Marion County, Indiana	11
24	904855	06/16/11	Weston Solutions, Inc.	U.S. EPA	Weston Solutions Title Search Report Re: West Vermont Water Contamination Site Michigan Plaza Property, Marion County, Indiana	11
25	904856	04/19/13	R.C. Minning & Associates, Inc. and Mundell & Associates, Inc.	AIMCO Michigan Meadows Holdings, LLC	Technical Response Re: "Technical Memorandum:" Analytical And Hydrogeological Evaluation, West Vermont Street Site, Speedway, Marion County, Indiana," Prepared For U.S. EPA By Weston Solutions, Inc.	160
26	904858	07/18/13	Lam, S., U.S. EPA	Billings, N., & P. Cappel, AIMCO	EPA Review Of Technical Response To "Technical Memorandum: Analytical And Hydrogeological Evaluation, West Vermont Street Site, Speedway, Marion County, Indiana," Prepared For U.S. EPA By Weston Solutions, Inc.	16

						Page 6
<u>NO.</u>	SEMS ID	<u>DATE</u>	<u>AUTHOR</u>	RECIPIENT	TITLE/DESCRIPTION	<u>PAGES</u>
27	437428	08/05/13	Lam, S., U.S. EPA	Karl, R., U.S. EPA	Enforcement Action Memorandum Re: Determination Of Threat To Public Health And The Environment And Selection Of Time-Critical Removal Actions At The West Vermont Drinking Water Contamination Site (PORTIONS OF THIS DOCUMENT HAVE BEEN REDACTED)	